
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 9/8/2009
Test to be performed:  Smoke Dyed Water X	Ground Condition:  Dry ✓ Damp ☐ Wet ☐	Supervisor: JAW
Manhole_ID: S04CC1017MH	Test ID: <u>D1032-027014</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S04CC1017MH
0			Water Level	
4			Dye Test Visible	DYE SEEN AT JOINT AT 8
7			Dye Test Visible	DYE SEEN AT JOINT
10			Dye Test Visible	SEEN AT JOINT 6-8
31.20000076			Abandoned Survey	DYE TEST COMPLETE